#### K

#### **ADA TRANSITION PLAN**

Prepared by the National League of Cities' Center for Education and Information Services Use this transition plan to document those architectural barriers that need to be removed. The deadline for completing this plan, not the changes, is July 26, 1992. After you have completed your self-evaluation checklists and architectural barriers checklist, you are now ready to prepare your transition plan. Use this form for each facility that needs structural modification. If your local government employs more than fifty people, you must retain this transition plan for three years and make it available for public inspection.

Date: April 26, 1993	
Name of person completing the plan:	
,	
Name of the ADA coordinator: <u>David M. Lykins - Community Services Department</u>	
Address of the facility: Multiple facilities in care of 735 8th St. S., Naples, FL	33940
List public services offered at this location:	
Parks and Recreation	
Marina	
Fishing Pie <sup>r</sup>	
Tennis Facility	
Community Centers - classes, theatre, athletics, camps	
Beach Accesses	
Passive Parks	



City of Naples, Florida

TO:

Dr. Richard L. Woodruff, City Manager

Kevin Rambosk, Assistant City Manager

**Department Directors** 

FROM:

Mary Kay McShane, Human Resources Director

DATE:

April 14, 1993

SUBJECT: A.D.A. Transition Plan

Attached is the master list of the City's Title III (Facilities Compliance) Transition Plan. This list was compiled from information provided by department coordinators. They have done an excellent job in analyzing facility needs as it pertains to ADA.

The A.D.A. law mandates that these facility changes be in place by January 1995. Department directors should ensure that funds are budgeted for these facility changes/alterations. I will follow up with department representatives periodically to monitor the status of implementation.

Thank you.

Approved by:

Maus Xaul

Mary Kay McShane

Human Resources Director

XC:

Department ADA Coordinators

Prepared by:

**Human Resources Officer** 

			Est. Cost
DEPT.	FACILITY/STRUCTURE CHANGE REQUIRED	of Comp.	of Comp.
FIRE Station #1	Restrooms: Modify/alter as required	• .	Unavail.
(Admin.)	Office Doors: Increase width to conform to guidelines	*	Unavail.
	(*Department is awaiting approval for remodeling or possibly new fire station and will conform to requirements)	•	
Station #2			
(Training	Entrance: Adjust threshold height (main entrance at rear of building)	Jan-95	Unavail.
Center)	Access: Contruct ramp or renovate entrance to accommodate wheelchair access	Jan-95	Unavail.
	Parking: Designated disabled area which conforms to width and gradient requirements	Jan-95	Unavail.
	Doors: Replace handles; adjust pressure	Jan-95	Minimal
	Obstacles: Remove/alter protruding obstacles in excess of 4" (i.e. water fountain)	Jan-95	Unavail.
	Restroom: Modify as required	Jan-95	Unavail.
POLICE	Public Parking Lot: Designate disabled parking area(s); install parking bumpers Ramp: Construct ramp/alter access to main entrance Employee Parking Lot: Designate disabled parking area(s); install parking bumpers Fire Alarms: Adjust to required height Doors: Adjust pressure	9/30/94 9/30/94 as needed Jan-95 9/30/94	Unavail. Unavail. Unavail. Unavail. Minimal
	Restroom Modifications: Adjust towel dispenser; insulate plumbing fixtures	9/30/93	Minimal
	and the second of the second o		

		Est. Date	Est. Cost
DEPT.	FACILITY/STRUCTURE CHANGE REQUIRED	of Comp.	of Comp.
COMM.			ŀ
DEVEL.	Access: Alter access area to employee work area (Building Division)	Jan-95	Unavail.
		or as needed	
	TDD Device: Install in central City Hall location	ASAP	
	(* Acquire using Community Development Block Grant funds.)		
	Building Code: Change verbage to reflect that alterations must be made in such a manner that they "not exceed 20% of the total cost alteration."	ASAP	None
	Doors: Adjust pressure; replace handles	Jan-95	Minimal
	Counter Height: Adjust to conform with guidelines	Jan-95	Unavail.
CITY CLERK			
(Office)	Door: Adjust pressure	ASAP	Minimal
	Counter: Adjust counter height to conform with guidelines	Jan-95	Unavail.
	Access: Alter area (counter and furniture) to allow for wheelchair passage	ASAP	Unavail.
(Council	Door: Adjust pressure; replace handles	ASAP	Minimal
Chamber)	Entrance: Adjust threshold height	Jan-95	Minimal
:	TDD: Purchase and install listening devices	ASAP	Unavail.
FINANCE	Counter Height: Adjust Customer Service and Cashier counters	Jan-94	•
	Office Doors: Increase width to conform to guidelines	Jan-94	* ]
	(* Department is currently planning renovation and will ensure compliance)	;	
	TDD Equipment: Install to accommodate hearing impaired customers	Jan-94	Unavail.
(Purchasing.)	No changes to this area required. Space is leased and reponsibility for compliance rests with		
	leasor. Recent modifications made prior to leasing are said to be in compliance	N/A	N/A

			Est. Cost
DEPT.	FACILITY/STRUCTURE CHANGE REQUIRED	of Comp.	of Comp.
UTILITIES		ĺ	1
(Administration)	Entrance: Adjust threshold to required height	Jan-95	Unavail.
	Door: Adjust pressure	ASAP	Minimal
	Restroom (Men's): Modify urinal as required	Jan-95	Unavail.
	Fire Extinguisher: Adjust to required height	Jan-95	Unavail.
	Signage: Adjust height of signs to approved standards	Jan-95	Minimal
	Thermostats: No need to adjust; operated by designated personnel only	N/A	N/A
(Equip. Svces.)	Restrooms: Adjust threshold at entrances	Apr-93	Minimal
	Thermostat: Adjust to required height	Apr-93	Minimal
	Fire Extinguisher: Adjust to required height	Apr-93	Minimal
	Parking: Designate handicapped parking space(s) as required	Mar-93	Minimal
(Maintenance)	No Public Access; Employees, by nature of the essential functions of the job, cannot be confined		
· ·	to a wheelchair; however, the WW control building restroom is a handicapped facility.	N/A	N/A
(WW Plant)	No Public Access	N/A	N/A
(Water Plant)	No Public Access; however, plant tours are given to the public on rare occasion. A ramp exists but disabled individuals may need assistance. This two-story building is accessible by elevator. No signage or audible tones for the elevator will be required because all tour participants will be accompanied at all times while in the building.	N/A	N/A
(Engineering)	Information forthcoming	*	
			,

		Est. Date	Est. Cost
DEPT.	FACILITY/STRUCTURE CHANGE REQUIRED	of Comp.	of Comp.
COMM.			
SVCES.			
City Hall	Water Fountain: Lower height	Jan-95	Minimal
	Telephone: Lower height	Jan-95	Tel. Co.
	Restroom Modifications: Lower paper towel dispenser; insulate plumbing fixtures; replace		
	handles on sinks	Jan-95	\$450
City Dock	Restroom Modifications: Adjust height of sinks; replace handles on sinks; lower urinal		
,	height; shower facilities inaccessible	Jan-95	\$650
	Telephone: Lower height	Jan-95	Tel. Co.
City Dock			
(Office)	Ramp: Construct access ramp	Jan-95	\$600
	Steps: Alter steps to conform to building code/ADA guidelines	Jan-95	\$300
Landings	Restroom Modifications: Make required installations (grab bars, etc.); adjust ramp gradient;		
	adjust urinal height	Jan-95	\$860
	Telephone: Lower height	Jan-95	Tel. Co.
Anthony			
Park	Playground: Inaccessible	Jan-95	\$15,000
u.	Restroom Modifications: Make required installations (grab bars, etc.); adjust towel dispenser		ĺ
	height; install handicap equipped toilets	Jan-95	\$360
Beach			
Access	Further research necessary; information forthcoming	Jan-95	Unavail.
		Page Total	\$18,220

		Est. Date	Est. Cost
DEPT.	FACILITY/STRUCTURE CHANGE REQUIRED	of Comp.	of Comp.
COMM.			
SVCES.			
Cambier	·		
Park	Basketball Court: Inaccessible	Jan-95	\$2,500
	Horseshoe Pits: Inaccessible	Jan-95	\$2,000
	Water Fountains: Lower height	Jan-95	\$500
	Playground: Inaccessible	Jan-95	\$15,000
	Walkway (to Pro Shop): Widen as required	Jan-95	\$3,000
	Playground Ramp: Adjust gradient to required ratio	Jan-95	\$500
(Norris Ctr.)	Auditorium Stage: Install ramp or hydrualic lift	Jan-95	\$3,000
	Doors: Install required closers; adjust to proper pressure	Jan-95	\$2,500
	Kitchen Area: Inaccessible	Jan-95	\$5,000
	Telephone: Lower height	Jan-95	Tel. Co.
	TDD: Purchase and install for programs and services	Jan-95	\$800
	Restroom Modifications: Alter stall width; install handicap equipped toilets and urinals; lower		
	mirrors and towel dispensers; insulate plumbing fixtures; replace sink handles	Jan-95	\$6,550
(Tennsi Ct.)	Restroom Modifications: Replace sink handles; lower mirrors and towel dispensers;		
	insulate plumbing fixtures.	Jan-95	\$1,100
(Ball Field)	Restroom Modifications: Install handicap equipped toilets; lower mirrors and towel dispensers;		
	insulate plumbing fixtures.	Jan-95	\$460
(Bandshell)	Wheelchair Pads: Install two (2) additional concrete pads	Jan-95	\$600
(Pavillion)	Ramp: Install ramp and handrail	Jan-95	\$2,500
(Pro Shop)	Ramp: Install ramp for accessibility	Jan-95	\$2,500
	Stairs: Replace stairs and handrails	Jan-95	\$800
	Water Fountains: Install accessible fountains	Jan-95	\$500
;		Page Total	\$49,810

-		Est. Date	Est. Cost
DEPT.	FACILITY/STRUCTURE CHANGE REQUIRED	of Comp.	of Comp.
COMM.			
SVCES.			
Lowdermilk			
Park	Ramp: Alter gradient of existing ramp to conform to guidelines	Jan-95	\$1,000
	Steps: Alter steps on East and West sides to meet building codes and ADA guidelines	Jan-95	\$1,000
	Walkways: Widen width of walkways to restrooms	Jan-95	Unavail
	Restroom Modifications: Install handicap equipped stalls; lower sinks, urinals, counter,	•	
	and towel dispensers	Jan-95	\$8,000
-	Shower Facilities: Inaccessible	Jan-95	\$1,400
	Concession Stand: Inaccessible	Jan-95	\$1,500
	Telephone: Adjust height	Jan-95	Tel. Co.
(Gazebo)	Handrails: Adjust to required height	Jan-95	\$400
	Ramp: Install ramp and paved pathway	Jan-95	\$3,400
River Park	Playground: Inaccessible	Jan-95	\$15,000
(Comm. Ctr.)	Kitchen area: Inaccessible	Jan-95	\$5,000
	Restrooms: Inaccessible; lower height of towel dispensers	Jan-95	\$2,500
	Entrance: Widen entrance; install required closures; adjust to proper pressure	Jan-95	\$600
	Stage Area: Install ramp or hydraulic lift	Jan-95	\$3,000
(Pavillion)	Restrooms: Inaccessible	Jan-95	\$1,500
(Pool)	Restrooms: Inaccessible	Jan-95	\$400
	Accessibility: Install ramp or lift	Jan-95	\$4,500
	Deck: Needs to be graded and leveled	Jan-95	\$1,000
(Office)	Inaccessible	Jan-95	\$200
		Page Total	\$50,400

<u> </u>		C-4 D-4-	Ic . O .
DEPT.	FACILITY/STRUCTURE CHANGE REQUIRED	Est. Date of Comp.	Est. Cost of Comp.
COMM.	Tridicit 1/0 modifice diving Redomes	or comp.	or comp.
SVCES.			
Pier	Restroom Modifications: Lower height of sinks, counters, and towel dispensers; adjust		
	height of grab rails, etc.	Jan-95	Minimal
	Ramp: Adjust gradient of walkover ramp to south restroom; install proper handrail	Jan-95	\$1,200
	Curbs: Need to cut and install walkway paths from designated parking spaces	Jan-95	\$500
[	Telephone: Lower height	Jan-95	Tel. Co.
	Signs: Handicapped parking signs difficult to see and need to be lowered	Jan-95	Unavail.
Fleischmann	Entrance: Adjust doorway to required width	Jan-95	\$5,000
Park .	Parking: Alter parking space width to adjust for required 5' accessway	Jan-95	\$100
	Kitchen: Area Inaccessible	Jan-95	\$4,000
1	Playground: Area and equipment Inaccessible	Jan-95	\$15,000
	TDD: Purchase and install listening devices		
		Jan-95	Unavail.
(Restroom,	Restrooms: Widen access area; stalls inaccessible; install handicap equipped toilets	Jan-95	\$2,500
Vending, &	Vending Area: Inaccessible	Jan-95	\$750
Storage Bldg.)	Water Fountain: Lower height	Jan-95	\$500
	Telephone: Lower height	Jan-95	Tel. Co.
(Ballfield	Entrances: Widen restroom and vending area entrances	Jan-95	\$2,250
Building)	Restrooms: Install handicap equipped toilets; lower towel dispensers	Jan-95	\$360
	Water Fountain: Lower height	Jan-95	\$500
	Second Floor: Accessible by stairs only	Jan-95	Unavail.
(Maint. Bldg.)	Restroom: Inaccessible; install handicapped toilet	Jan-95	\$180
		Page Total	\$32,840

	FACILITY/CTDLICTLIDE CLIANCE DECLUDED	Est. Date of Comp.	
DEPT. ALL CITY BUILDINGS	FACILITY/STRUCTURE CHANGE REQUIRED	or comp.	or Comp.
and FACILITIES	Door Handles: Replace door handles with levers	Jan-95	Unavail.
	Signage: Purchase and install raised letter and/or numbered signs for all rooms, offices, and facilities.	Jan-95	Unavail.
	Elevator: Purchase and install signage and audible tones as required	Jan-95	Unavail.
4			