
ATKINS			East Naples Bay Dredging Project Weekly Summary Report							4030 W Boy Scout Blvd Tampa, FL 33607	
Location:			ast Naple Iaples, F			Weel	k:	40	Daily Reports:	246-251	
Project Name:	East Naples Bay Dredging					Wee Startir		04/16/12	Phase:	1	
Project Number:	100022567					Dates	s:	Apr 16, 2	012 through Ap	or 21, 2012	
Report Prepared By:	Matthew Starr – Atkins										
Weather:											
Max High:	85 °F										
Max Low:	64 °F										
Precipitation:	0.53 inches Wind Speed: Max			Max Av	verage: 7.1 mph Maximum: 15.2 mph				mph		
Tides:	Max H	ligh:	13:18)4/21/12	2.9 F	T N	Min Low: 20		32 04/21/12	-0.2 FT	
General Contractor:	Energy Resources		Work Description:		Dredging in Canals X-X and survey cleanup			leanup			
	Ge	neral C	ontracto	rs Emplo	oyees & E	Equipme	nt U	sed on Pr	oject:		
Employee	Major Equipment Used:										
Lane	Dredge										
Jimmy	Seismographs, boat										
Rob	Boat										
Teo	Trackh	noe									

Subcontractors Employees & Equipment Used on Project:						
Company	Stemic Marine Construction					
Employee	Major Equipment Used:					
Aaron	Excavator					
Vinny	Dump truck					
Oliver	Barge					
Scott	Excavator					
Armando	Barge					



Summary of Work Accomplished

Contractor:

Energy Resources and Stemic Marine Construction

- Energy Resources addressing high spots in Canal BB-BB and CC-CC per survey results
- Energy Resources maintained dewatering berm at spoil site
- Energy Resources in compliance with permits and conducted turbidity monitoring
- Energy Resources moved dredge material from dewatering cell into drying area with trackhoe for mixing
- Energy Resources deployed seismographs on both sides of Canal X-X to monitor rock removal
- Stemic conducting rock removal in Canal X-X
- Stemic addressing high spots in Canal BB-BB and DD-DD per survey results

Engineer:

ATKINS

- Onsite at dewatering area and in Canals X-X, DD-DD, CC-CC, and BB-BB, during dredging providing CEI services
- Conducted turbidity monitoring
- Phone calls and speaking with residents onsite regarding project

I certify that I have performed the Resident Inspector's duties this date on the above described work, that through my presence and personal observation of the work and through standard testing methods, I certify the contractor is accomplishing the contract work in accordance with the requirements of the plans and specifications.

Resident's Signature	11/S-	Date	04/21/2012





EAST NAPLES BAY DREDGING (100022567) WEEKLY SUMMARY REPORT