| ΛΤΚΙΝ | IS | East Naples Bay Dredging Project Weekly Summary Report | | | | | | | 4030 W Boy Scout Blvd Tampa, FL 33607 | |
|------------------------|---------------------------------------|---|-----------|--------------------------------------|---------------------|--------------|-----------------------------------|--------|--|----------------|
| Location: | East Naples Bay Naples, Florida | | | | We | ek: | 41 | | Daily Reports: | 252-256 |
| Project Name: | East Naples Bay Dredging | | | ng | | eek ting: | 04/23 | 8/12 | Phase: | 1 |
| Project Number: | 100022567 | | | | Dat | tes: | Apr 23, 2012 through Apr 27, 2012 | | | |
| Report Prepared By: | Matthew Starr – Atkins | | | | | | | | | |
| | | | | | | | | | | |
| Weather: | | | | | | | | | | |
| Max High: | 86 ° F | | | | | | | | | |
| Max Low: | 52 ° F | | | | | | | | | |
| Precipitation: | 0.00 inches | inches Wind Speed: Max Ave | | | erage: 22.0 mph Max | | | Maxi | kimum: 22.9 mph | |
| Tides: | Max High: | 14:07 | 04/23/12 | 2.9 F | ٠T | Min L | .ow: | 21:4 | 5 04/23/12 | -0.2 FT |
| General Contractor: | Energy Resources Work Description: | | | Cleanup in DD, Y, W, V and Main B/B1 | | | | | | |
| | | | • | | | | | | | |
| | General | Contracte | ors Emplo | oyees & I | Equipn | nent U | lsed on | n Proj | ect: | |
| Employee | Major Equipment Used: | | | | | | | | | |
| Lane | Dredge | | | | | | | | | |
| Jimmy | Seismographs, boat | | | | | | | | | |
| Rob | Boat | | | | | | | | | |
| Teo | Dredge | | | | | | | | | |
| Mike | Trackhoe | | | | | | | | | |
| | 1 | | | | | | | | | |

| Subcontractor | Subcontractors Employees & Equipment Used on Project: | | | | | |
|---------------|---|--|--|--|--|--|
| | | | | | | |
| Company | SteMic Marine Construction | | | | | |
| Employee | Major Equipment Used: | | | | | |
| Aaron | Excavator | | | | | |
| Vinny | Dump truck | | | | | |
| Oliver | Barge | | | | | |
| Scott | Excavator | | | | | |
| Armando | Barge | | | | | |
| | | | | | | |
| | | | | | | |

ATKINS

| Summary of Work Accomplished | | | | | | |
|--|--|---------------------|------------|--|--|--|
| Contractor: | Energy Resources and SteMic Marine Construction |) | | | | |
| Energy Energy Energy SteMic | Resources addressing high spots in Canal W-W and V-N Resources maintained dewatering berm at spoil site Resources in compliance with permits and conducted tu Resources deployed seismographs to monitor rock remo addressing rock high spots in Canals DD-DD and Y-Y per addressing sediment high spots in Main B/B1 | rbidity mor oval | itoring | | | |
| Engineer: | ATKINS | | | | | |
| providir • Conduc | at dewatering area and in Canals DD-DD, Y-Y, V-V, W-W ng CEI services cted turbidity monitoring neck of survey results to provide punchlist of items to Ene s | | | | | |
| I certify that I have performed the Resident Inspector's duties this date on the above described work, that through my presence and personal observation of the work and through standard testing methods, I certify the contractor is accomplishing the contract work in accordance with the requirements of the plans and specifications. | | | | | | |
| Resident's | on/C | | | | | |
| Signature | 112 | Date | 04/27/2012 | | | |



Rock cleanup from Canal DD-DD

