ΛΤΚΙΝ	IS	East Naples Bay Dredging Project Weekly Summary Report							4030 W Boy Scout Blvd Tampa, FL 33607	
Location:	East Naples Bay Naples, Florida			We	ek:	55		Daily Reports:	313-314	
Project Name:	East Naples Bay Dredging					eek ting:	07/30/12	2	Phase:	1
Project Number:	100022567				Dat	tes:	July 30, 2012 to August 03, 2012			
Report Prepared By:	Matthew Starr – Atkins									
Weather:										
Max High:	91 ° F									
Max Low:	76 ° F									
Precipitation:	0.72 inche	s Wind	Wind Speed: Max Aver			rage: 6.1 mph Max		axin	kimum: 17.1 mph	
Tides:	Max High:	12:45	08/01/12	3.5 F	T	Min Low: 19:		:52	08/01/12	-0.4 FT
General Contractor:	Energy Resources Work Description:			Mixing dredge material						
	Genera	I Contracto	ors Emple	oyees & E	Equipn	nent U	sed on P	roje	ect:	
Employee	Major Equipment Used:									
Teo	Trackhoe									
Jimmy	Trackhoe,	seismograp	hs							

Subcontractors Employees & Equipment Used on Project:					
Company	SteMic Marine Construction				
Employee	Major Equipment Used:				
Aaron	Barge				
Brad	Boat				



	Summary of Work Accomplished					
Contractor:	Energy Resources and SteMic Marine Construction	1				
with dry	Resources drying and mixing dredged material at spoil s dredge material working on additional rock in Canal V-V	site, sendin	g dumptrucks to landfill			
Engineer:	ATKINS					
	at spoil site during mixing and trucking n Canal V-V during rock removal					
I certify that I have performed the Resident Inspector's duties this date on the above described work, that through my presence and personal observation of the work and through standard testing methods, I certify the contractor is accomplishing the contract work in accordance with the requirements of the plans and specifications.						
Resident's Signature	MS-	Date	08/03/2012			