



**WEEKLY SUMMARY REPORT – CONTRACT WEEK 02**  
**21-036 EAST NAPLES BAY**  
**DREDGING AND ROCK REMOVAL PROJECT**



Date: <b>10/25/2021 to 10/29/2021</b>			
Inspectors: <b>Sam Boyd</b>	Stantec PIN: <b>2028113191</b>	Accidents <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Days of Week: <b>Monday to Friday</b>	Contract Days: <b>8 to 12</b>	Total Days: <b>365</b>	Accident Report #: <b>N/A</b>
Canal(s) Worked In: <b>CC-CC</b>		Stations Worked Between: <b>N/A</b>	

General
Remarks
<p><b>#1 – Prime Contractor – Quality Enterprises:</b></p> <p><u>Monday 10-25-2021:</u></p> <ul style="list-style-type: none"> <li>No onsite activity.</li> </ul> <p><u>Tuesday 10-26-2021:</u></p> <ul style="list-style-type: none"> <li>No onsite activity.</li> </ul> <p><u>Wednesday 10-27-2021:</u></p> <ul style="list-style-type: none"> <li>No onsite activity.</li> </ul> <p><u>Thursday 10-28-2021:</u></p> <ul style="list-style-type: none"> <li>No onsite activity.</li> </ul> <p><u>Friday 10-29-2021:</u></p> <ul style="list-style-type: none"> <li>Contractor’s equipment is staged in canal CC-CC between stations 13+00 and 14+00. This equipment includes an excavator on the barge and a push boat.</li> </ul> <p><b>Note: Daily reports with pictures attached for the week.</b></p>



**DAILY REPORT OF CONSTRUCTION**  
 21-036 EAST NAPLES BAY  
 DREDGING AND ROCK REMOVAL PROJECT



Date: <b>10/25/2021</b>			
Inspectors: <b>SB</b>	Stantec PIN: <b>2028113191</b>	Accidents <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Day of Week: <b>Monday</b>	Contract Day: <b>8/365</b>	Week: <b>2</b>	Accident Report #: <b>N/A</b>
High Temp (°F): <b>84°F</b>	AM Conditions: <b>Sunny</b>	PM Conditions: <b>Sunny</b>	High Tide: <b>4:56 PM – 2.9 ft</b>
Low Temp (°F): <b>66°F</b>	Wind: <b>10mph</b>	Wind: <b>17mph</b>	Low Tide: <b>10:06 AM – 0.4 ft</b>
Canal Worked In: <b>N/A</b>	Stations Worked Between:	<b>N/A</b>	

**General**

**#1 – Prime Contractor – Quality Enterprises:**

- No activity.

**Planned look ahead of activities for next week:**

- Canal CC-CC scheduled begin Friday 10/29.

**Contractor(s) and Personnel**

#	Name	Type	#	Hrs.	Type	#	Hrs.	Type	#	Hrs.
1	Prime: <b>Quality Enterprises</b>	PM	0	0	Field Supervisor	0	0	Foreman	0	0
		Skilled Laborer	0	0	Unskilled Laborer	0	0	Safety Director	0	0

**Equipment**

Cont/ Sub #	Equipment ID	Description	# Pieces	# Used	Total Hours Used
1	-	<b>Barge</b>	0	0	0
1	-	<b>Excavator</b>	0	0	0
1	-	<b>Push Boat</b>	0	0	0
1	-	<b>Support Boats</b>	0	0	0
1	-	<b>Dump truck</b>	0	0	0

**Visitors**

Name	Company	Hours at Job Site	
		From:	To:

**Inspector Name and Position**

Inspector Name and Position	Hours at Job Site/Office		Total Hours
Sam Boyd, EIT – Inspector	From: N/A	To: N/A	0



**DAILY REPORT OF CONSTRUCTION**  
 21-036 EAST NAPLES BAY  
 DREDGING AND ROCK REMOVAL PROJECT



Date: <b>10/26/2021</b>			
Inspectors: <b>SB</b>	Stantec PIN: <b>2028113191</b>	Accidents <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Day of Week: <b>Tuesday</b>	Contract Day: <b>9/365</b>	Week: <b>2</b>	Accident Report #: <b>N/A</b>
High Temp (°F): <b>84°F</b>	AM Conditions: <b>Sunny</b>	PM Conditions: <b>Sunny</b>	High Tide: <b>6:05 PM – 2.3 ft</b>
Low Temp (°F): <b>66°F</b>	Wind: <b>10mph</b>	Wind: <b>17mph</b>	Low Tide: <b>10:58 AM – 0.5 ft</b>
Canal Worked In: <b>N/A</b>	Stations Worked Between:	<b>N/A</b>	

**General**

**#1 – Prime Contractor – Quality Enterprises:**

- No activity.

**Planned look ahead of activities for next week:**

- Canal CC-CC scheduled begin Friday 10/29.

**Contractor(s) and Personnel**

#	Name	Type	#	Hrs.	Type	#	Hrs.	Type	#	Hrs.
1	Prime: <b>Quality Enterprises</b>	PM	0	0	Field Supervisor	0	0	Foreman	0	0
		Skilled Laborer	0	0	Unskilled Laborer	0	0	Safety Director	0	0

**Equipment**

Cont/ Sub #	Equipment ID	Description	# Pieces	# Used	Total Hours Used
1	-	<b>Barge</b>	0	0	0
1	-	<b>Excavator</b>	0	0	0
1	-	<b>Push Boat</b>	0	0	0
1	-	<b>Support Boats</b>	0	0	0
1	-	<b>Dump truck</b>	0	0	0

**Visitors**

Name	Company	Hours at Job Site	
		From:	To:

**Inspector Name and Position**

Inspector Name and Position	Hours at Job Site/Office		Total Hours
Sam Boyd, EIT – Inspector	From: N/A	To: N/A	0



**DAILY REPORT OF CONSTRUCTION**  
 21-036 EAST NAPLES BAY  
 DREDGING AND ROCK REMOVAL PROJECT



Date: <b>10/27/2021</b>			
Inspectors: <b>SB</b>	Stantec PIN: <b>2028113191</b>	Accidents <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Day of Week: <b>Wednesday</b>	Contract Day: <b>10/365</b>	Week: <b>2</b>	Accident Report #: <b>N/A</b>
High Temp (°F): <b>84°F</b>	AM Conditions: <b>Sunny</b>	PM Conditions: <b>Sunny</b>	High Tide: <b>7:15 PM – 2.3 ft</b>
Low Temp (°F): <b>66°F</b>	Wind: <b>10mph</b>	Wind: <b>17mph</b>	Low Tide: <b>12:03 PM – 0.6 ft</b>
Canal Worked In: <b>N/A</b>	Stations Worked Between:	<b>N/A</b>	

**General**

**#1 – Prime Contractor – Quality Enterprises:**

- No activity.

**Planned look ahead of activities for next week:**

- Canal CC-CC scheduled begin Friday 10/29.

**Contractor(s) and Personnel**

#	Name	Type	#	Hrs.	Type	#	Hrs.	Type	#	Hrs.
1	Prime: <b>Quality Enterprises</b>	PM	0	0	Field Supervisor	0	0	Foreman	0	0
		Skilled Laborer	0	0	Unskilled Laborer	0	0	Safety Director	0	0

**Equipment**

Cont/ Sub #	Equipment ID	Description	# Pieces	# Used	Total Hours Used
1	-	<b>Barge</b>	0	0	0
1	-	<b>Excavator</b>	0	0	0
1	-	<b>Push Boat</b>	0	0	0
1	-	<b>Support Boats</b>	0	0	0
1	-	<b>Dump truck</b>	0	0	0

**Visitors**

Name	Company	Hours at Job Site	
		From:	To:

**Inspector Name and Position**

Inspector Name and Position	Hours at Job Site/Office		Total Hours
Sam Boyd, EIT – Inspector	From: N/A	To: N/A	0



**DAILY REPORT OF CONSTRUCTION**  
 21-036 EAST NAPLES BAY  
 DREDGING AND ROCK REMOVAL PROJECT



Date: <b>10/28/2021</b>			
Inspectors: <b>SB</b>	Stantec PIN: <b>2028113191</b>	Accidents <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Day of Week: <b>Thursday</b>	Contract Day: <b>11/365</b>	Week: <b>2</b>	Accident Report #: <b>N/A</b>
High Temp (°F): <b>84°F</b>	AM Conditions: <b>Sunny</b>	PM Conditions: <b>Sunny</b>	High Tide: <b>8:16 PM – 2.4 ft</b>
Low Temp (°F): <b>66°F</b>	Wind: <b>10mph</b>	Wind: <b>17mph</b>	Low Tide: <b>1:11 PM – 0.7 ft</b>
Canal Worked In: <b>N/A</b>	Stations Worked Between:	<b>N/A</b>	

**General**

**#1 – Prime Contractor – Quality Enterprises:**

- No activity.

**Planned look ahead of activities for next week:**

- Canal CC-CC scheduled begin Friday 10/29.

**Contractor(s) and Personnel**

#	Name	Type	#	Hrs.	Type	#	Hrs.	Type	#	Hrs.
1	Prime: <b>Quality Enterprises</b>	PM	0	0	Field Supervisor	0	0	Foreman	0	0
		Skilled Laborer	0	0	Unskilled Laborer	0	0	Safety Director	0	0

**Equipment**

Cont/ Sub #	Equipment ID	Description	# Pieces	# Used	Total Hours Used
1	-	<b>Barge</b>	0	0	0
1	-	<b>Excavator</b>	0	0	0
1	-	<b>Push Boat</b>	0	0	0
1	-	<b>Support Boats</b>	0	0	0
1	-	<b>Dump truck</b>	0	0	0

**Visitors**

Name	Company	Hours at Job Site	
		From:	To:

**Inspector Name and Position**      **Hours at Job Site/Office**      **Total Hours**

Sam Boyd, EIT – Inspector	From: N/A	To: N/A	0
---------------------------	-----------	---------	---



**DAILY REPORT OF CONSTRUCTION**  
 21-036 EAST NAPLES BAY  
 DREDGING AND ROCK REMOVAL PROJECT



Date: <b>10/29/2021</b>			
Inspectors: <b>SB</b>	Stantec PIN: <b>2028113191</b>	Accidents <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	
Day of Week: <b>Friday</b>	Contract Day: <b>12/365</b>	Week: <b>2</b>	Accident Report #: <b>N/A</b>
High Temp (°F): <b>84°F</b>	AM Conditions: <b>Sunny</b>	PM Conditions: <b>Sunny</b>	High Tide: <b>7:14 AM – 2.5 ft</b>
Low Temp (°F): <b>66°F</b>	Wind: <b>10mph</b>	Wind: <b>17mph</b>	Low Tide: <b>2:12 PM – 0.7 ft</b>
Canal Worked In: <b>CC-CC</b>	Stations Worked Between:	<b>N/A</b>	

General	
<b>#1 – Prime Contractor – Quality Enterprises:</b>	
<ul style="list-style-type: none"> <li>Contractor’s equipment is staged in canal CC-CC between stations 13+00 and 14+00. This equipment includes an excavator on the barge and a push boat.</li> </ul>	

Contractor(s) and Personnel										
#	Name	Type	#	Hrs.	Type	#	Hrs.	Type	#	Hrs.
1	Prime: <b>Quality Enterprises</b>	PM	<b>0</b>	<b>0</b>	Field Supervisor	<b>0</b>	<b>0</b>	Foreman	<b>0</b>	<b>0</b>
		Skilled Laborer	<b>0</b>	<b>0</b>	Unskilled Laborer	<b>0</b>	<b>0</b>	Safety Director	<b>0</b>	<b>0</b>

Equipment					
Cont/ Sub #	Equipment ID	Description	# Pieces	# Used	Total Hours Used
<b>1</b>	<b>n/a</b>	<b>Barge</b>	<b>1</b>	<b>0</b>	<b>0</b>
<b>1</b>	<b>CAT 323</b>	<b>Excavator</b>	<b>1</b>	<b>0</b>	<b>0</b>
<b>1</b>	<b>FL6223TB</b>	<b>Push Boat</b>	<b>1</b>	<b>0</b>	<b>0</b>
<b>1</b>	<b>FL2474PP</b>	<b>Support Boat</b>	<b>0</b>	<b>0</b>	<b>0</b>

Visitors			
Name	Company	Hours at Job Site	
		From:	To:

Inspector Name and Position	Hours at Job Site/Office		Total Hours
Sam Boyd, EIT – Inspector	From: 1:30 PM	To: 2:30 PM	1



- Entrance to Canal CC-CC.





- Entrance to Canal CC-CC.





- Empty lot on Canal CC-CC between stations 13+00 and 14+00.





- Contractor's equipment (323 excavator and barge) staged in canal CC-CC at station 13+50.





- Contractor's equipment (push boat) staged in canal CC-CC at station 13+50.

